CDM Smith Daily Status Report

Site Name/Location: Cabo Rojo Groundwater Contamination Site, Cabo Rojo Puerto Rico

DATE: 4/16/13 **WEATHER:** 98 Degrees F, Sunny

PERSONNEL ONSITE

CDM Smith

Frances Delano Patrick Connelly José Reyes

CDM Subcontractor

Joel Alvarado, driller Luis F. Santiago, driller Orlando Marrero, driller

FIELD EVENT: Continue sampling soil vapor

FIELD WORK PERFORMED:

- Equipment was calibrated and checked
- Field GC Screening results for RETO Plant:
 - RP-SV-06 / 5.5 6 ft bgs DCE .0.191 ppm [PID readings: CO 28.0/ VOCs 4.7]
 - RP-SV-26 (duplicate of 06) ND
 - RP-SV-07/7.5-8 ft bgs ND [PID readings: CO 16/ VOCs 3.8]
 - RP-SV-04/7.5-8 ft bgs PCE 0.805 ppm [PID readings: CO 196/VOCs 9.1]
 - RP-SV-03/6-6.5 ft bgs PCE 0.024 ppm [PID readings: CO 709/ VOCs 3.3]
- Field GC Screening results for Unfinished Strip Mall
 - US-SV-01/6.5-7 ft bgs PCE 0.150 ppm [PID readings: CO 1018/ VOCs 10.3]
 - US-SV-03/6-6.5 ft bgs PCE 0.024 ppm[PID readings: CO 26/ VOCs 5.4]
 - US-SV-04/7.5-8 ft bgs DCE 0.199 ppm [PID readings: CO 982/ VOCs 7.9]
 - US-SV-05/5-5.5 ft bgs PCE 0.132 [PID readings: CO 342/ VOCs 4.0]
 - US-SV-06/7.5-8 ft bgs PCE 0.014 / TCE 1.875 [PID readings: CO 306/ VOCs 6.4]
 - US-SV-07/7.5 8 ft bgs ND [PID readings: CO 982/ VOCs 7.9]
 - US-SV-08/7.5 8 ft bgs ND [PID readings: CO 464/VOCs 7.3]
 - US-SV-09/5.5 6 ft bgs ND [PID readings: CO 61/ VOCs 3.3]
 - US-SV-10/4.5 5 ft bgs ND [PID readings: CO 277/ VOCs 6.5]
- Confirmatory Sample collected:
 - US-SV-03C
- Sampled Confirmatory sample will be hold until next facility is sampled and then shipped together.
- Received IDW rollof and tanker (see note below) from Aqua Clean Ships Caribe Inc.
- Health and Safety meeting
- Security arrived to site

Proposed next day event:

 Complete soil vapor sampling at Unfinished Strip Mall (US-SV-02) and start/complete Raul Lugo Storage Yard

Proposed next days/week schedule:

- Apr.18/2013 Start sampling soil and groundwater at Cabo Rojo Dry Cleaners
- Apr.19/2013 Complete sampling soil and groundwater at Cabo Rojo Dry Cleaners



Site Name/Location: Cabo Rojo Groundwater Contamination Site, Cabo Rojo Puerto Rico

- Apr.22/2013 Start soil vapor sampling at PRIDCO west (Propper International, active)
- Apr. 23/2013 Complete soil vapor sampling at PRIDCO west (Propper International, inactive)
- Apr. 24/2013 Start /complete sampling at SerranoII Dry Cleaners
- Apr. 25/2013 Start/complete sampling at Walgreens
- Apr.26/2013 Possibly short day to compensate for extended sampling day at Walgreens and if needed finish sampling at Serrano II

MISCELLANEOUS:

- IDW subcontractor did not provide a clean certification for the tanker. José de León, the contact person at Aqua Clean Ships Caribe, Inc. was informed but he did not now that the certification was necessary. We accepted the tanker with the authorization of the Site Manager but it will not be used until we clarify this situation with Capitol.
- The IDW subcontractor was requested to provide cover for the rolloff which he provided.
- PRIDCO has assigned an environmental specialist to be present during our sampling at their facilities. She has requested a copy of our workplan but was told that any request for documentation has to be directed to the EPA RPM. We provided her with our proposed schedule for the upcoming sampling at PRIDCO.
- Coordinated with Raul Lugo for starting sampling at his property
- Will leave a temporary lock at the Unfinish Strip Mall to easy access in the morning for the sampling of the last sample
- Coordinated the access to Cabo Rojo Dry Cleaners for Thursday and Friday
- Received a call from Felix Soler to inform me that he had corrected the noted issues. I informed
 him that the documented visit was forward to EPA and EPA to PREQB. They will be contacting
 him.
- Field GC chromatographs were visibly shifting to the right as if the peaks were developing with delays. According to the Pine technician the column is now clean from any remnants of past uses and from now on the reading will be more accurate. However, the samples will had to be reanalyzed after a complete flush of the instrument run over night.